



Dominion

DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: JAN. 27, 2016

WEATHER: 30, SUNNY

INSPECTED BY: K. ACREE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	2:14 PM → SNOW COVERED ASSUMED NO CHANGE;
Erosion	N	N	NO STANDING WATER AGAINST SAND BAGS; SAND BAGS APPEARED TO BE IN-PLACE; RIPRAP APPEARED TO BE IN-PLACE
Low Point, B dike*			
Flow	N	N	2:11 PM → SNOW COVERED ASSUMED NO CHANGE; STANDING
Erosion	N	N	WATER AGAINST SAND BAGS SAND BAGS APPEARED TO BE IN-PLACE. STANDING WATER BETWEEN SAND BAGS & OUTSIDE PART OF EMBANKMENT (SMALL AMOUNT), BUT NO STANDING WATER BETWEEN OUTSIDE ^{INSIDE} PORTION OF EMBANKMENT AND SAND BAGS
Outfall water surface El. (top of stoplogs to water)			2:00 PM → SNOW APPROX. 3 FT. FROM WEIR; RIGHT SIDE OF WEIR WAS MOIST, NO FLOW AND NO STANDING WATER AGAINST WEIR

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): - APPROX. 6" TO 12" OF SNOW ACCUMULATION OVER POND A, B, & C LOCATIONS

- LOW POINT, (DIKE) SAND BAGS APPEARED TO BE IN-PLACE & NO STANDING WATER AGAINST SAND BAGS; SNOW COVERED ASSUMED NO CHANGE

- STANDING WATER AT TOE OF INSIDE EMBANKMENT OF POND C (TYPICAL OF POND A & B)

- STANDING WATER AT TOE OF EMBANKMENT AS NOTED BELOW.

